

**DEAN ROAD BETWEEN SOILWELL AND OLDCROFT, FOREST OF
DEAN, GLOUCESTERSHIRE**

WORK CARRIED OUT BETWEEN 25 JULY 2016 AND 23 OCTOBER 2016

ILLUSTRATIONS




Fig. 1 Site location

© Gloucestershire County Council: Reproduced from Hoyle 2016, Fig 1




Fig. 2 Site plan



Fig. 3 Kerbed road looking north (TP 4 is also visible)



Fig. 4 Kerbed road looking south



Fig. 5 Kerb stones



Fig. 6 line of kerb stones looking north



Fig. 7 line of kerb stones looking south



Fig. 8 Cobbled surface looking east (TP1 is at the bottom of the photograph)



Fig. 9 Intersection of cobbled surface with kerbed road looking west (TP5 is at the bottom of the photograph)



Fig. 10 Test Pit 1 looking east



Fig. 11 Test Pit 5 looking north



Fig. 12 Test Pit 6 looking south



Fig. 13 Test Pit 2 looking west



Fig. 14 Test Pit 2 looking north



Fig. 15 Test Pit 2 - larger irregularly laid stones removed from sub base



Fig. 16 Test Pit 2 southern edge - cobbled surface



Fig. 17 Test Pit 3 looking east



Fig. 18 Test Pit 4 looking east



Fig. 19 Test Pit 4 looking south



Fig. 20 Test Pit 7 looking west



Fig. 21 Test Pit 10 looking east




Fig. 22 Profile of road surfaces looking south including profile in TP4




Fig. 23 Possible divergence of routes

© Gloucestershire County Council and Forestry Commission: Reproduced from Hoyle 2016, Fig 7



Fig. 24 Some of the diggers